


MEASUREMENT OF ABSORPTION ANGLE OF TFT LCD POLARIZERS


Step1:

Take the Polarizer which you want to test and the ELSIN Polarizer Tester

POLARIZER




POLARIZER TESTER



www.elsin.eu

Step2:

Make orientation of Polarizer. Be sure that upper protective film is really on the top !




Recommendation how to identify the upper side :

- Find the marker in the right upper corner (if possible)
- Test upper film - if there is an adhesive on the bottom of upper film than it is protective film

www.elsin.eu

Step 3:
Put the tester tightly under the Polarizer



Step 4:
Read the number in the lightest rectangle. It shows the correct absorption angle of Polarizer

